V. WASTE RELATED INFORMATION (continued)

3. LIST SUBSTANCES OF GREATEST CONCERN WHICH MAY BE ON THE SITE (place in descending order of hezerd).

In 1984 PCBs were discovered in the evap. pond, sump, and at locations along the drainage pipe. The site was cleaned up between 9/15/85 and 10/15/86.

VI. HAZARD DESCRIPTION				
A. TYPE OF HAZARD	B. POTEN- TIAL HAZARD (mark 'X')	C. ALLEGED INCIDENT (mark 'X')	D. DATE OF INCIDENT (mo.,day,yr.)	E. REMARKS
1. NO HAZARD	Х	1.14		No hazard observed on inspection
2. HUMAN HEALTH				
3. NON-WORKER INJURY/EXPOSURE				
4. WORKER INJURY				
B. CONTAMINATION B. OF WATER SUPPLY				
d. CONTAMINATION				
7. CONTAMINATION OF GROUND WATER				
S. CONTAMINATION S. OF SURFACE WATER				
9. DAMAGE TO FLORA/FAUNA				
10. FISH KILL				
11. CONTAMINATION				
12. NOTICEABLE COORS				
13. CONTAMINATION OF SOIL				
14. PROPERTY DAMAGE				
15. FIRE OR EXPLOSION				
16. SPILLS/LEAKING CONTAINERS/ RUNOFF/STANDING LIQUIDS				
17. SEWER, STORM				
te. EROSION PROBLEMS				
19. INADEQUATE SECURITY				
20. INCOMPATIBLE WASTES				
21. MIDNIGHT DUMPING				
2 2. OTHER (epocity):				

EPA Form T2070-2 (10-79)

PAGE 3 OF 4

Continue On Reverse

EPA Form T2070-2 (10-79)

information on the first page of this form.

PAGE 4 OF 4

